



Intertek Testing Services

Caleb Brett SUAL TANK INSPECTION REPORT

Vessel : ETT-112
Port/Terminal : HERCULES SHIPYARD
Product/Cargo : 99.9% CYCLOHEXANE

Your Ref :
Our Ref : FP/97-5235
Date : 05/02/97


Tank No.	Tank Coating	Last Cargo	Second Last Cargo	Third Last Cargo	Date	Time	Accept/Reject (*)	Reason For Rejection
1	Mild Steel	CYCLOHEXANE	CYCLOHEXANE	CYCLOHEXANE	05/02/97	17:35	A	
2	Mild Steel	CYCLOHEXANE	CYCLOHEXANE	CYCLOHEXANE	05/02/97	17:35	A	
3	Mild Steel	CYCLOHEXANE	CYCLOHEXANE	CYCLOHEXANE	05/02/97	17:35	A	

Method Said To Have Been Used To Clean Tanks:

All cargo tanks and pipelines were stripped and blown dry.

Information regarding previous cargoes, tank coatings, and cleaning methods was obtained from vessel personnel and cannot be guaranteed as accurate by Caleb Brett, and no liability can be assumed for errors resulting from improper information supplied. This report, of necessity, is based on such information.

* The cleanliness of inspected tank(s) is/are based on visual inspection of tank surfaces and line system at accessible areas only. This document does not cover the cleanliness of tank surfaces and line system at inaccessible spots and/or possible release of components of previous cargoes during loading, discharge, or transport of the cargo in question, for which the vessel is fully responsible. Suitability of tank coating for intended cargo must be guaranteed by vessel's owner or by suppliers of coating.


ITS - Caleb Brett